

SELF PERFORMED MAINTENANCE/REPAIR

Date 01/02/2014

Scheduled Service Repair Acc'y Install Other

| | | | | | | | | |
|----------|------|------|----|-------|-------|-----|-------|--------|
| Vehicle: | | | | | | | | |
| Year | 2009 | Make | HD | Model | FLHTC | Vin | Miles | 32,948 |

Job Description:

JOB 1- OIL AND FILTER CHANGE
 JOB 2- INSTALL NEW OIL TEMPERATURE GAUGE REC'D FOR CHRISTMAS

Parts Used:

| QTY | Part Number | Description | Each | Ext |
|-----|-------------|-----------------------------|-------|-------|
| 1 | 63798-99A | OIL FILTER | 13.95 | 13.95 |
| 4 | 62600007 | 20w-50 OIL | 7.49 | 29.96 |
| 1 | 11105 | OIL PLUG (DRAIN) "O" RING | 1.14 | 1.14 |
| 1 | 70900283 | OIL TEMPERATURE GAUGE BLACK | GIFT | 0 |
| | | | | 0 |
| | | | | 0 |

*ROAD TESTED NO LEAKS NOTED -
 INST. CALL FOR LOCTITE 565, 3HD
 DID NOT HAVE & ADVISED USING
 TEFLON TAPE ON SENSOR & BUSHING*

| | |
|-----------|-------|
| Sub Total | 45.05 |
| Tax | 3.83 |
| Job Total | 48.88 |

Labor Hours 2.00

Note:

NOTICED OIL LEAK FROM NEAR TIMING COVER- WILL NEED TO KEEP AN EYE ON THIS AREA.
 REPLACING AIR TEMP GAUGE WITH OIL TEMP GAUGE, FAIRING PORTION NOT AS EASY AS IT
 LOOKS.